Suzanne Steab - April 2011 Inspection Reports

From:

Karl Houskeeper

To:

rnetz@emerytelcom.net

Date:

5/4/2011 3:21 PM

Subject:

April 2011 Inspection Reports

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: SCA April 2011.pdf; SPWF April 2011.pdf

Rusty,

Attached are the April 2011 inspection reports for SCA and SPWF.

Thanks,

Karl



GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

HCHAEL K. STYLER

Division of Oil, Gas and Mining

JOHN R. BAZA

Representativ	es Present During the Inspection:
Company	Rusty Netz
OGM	Kevin Lundmark
OGM	Karl Houskeeper

Inspection Report

Permit Number:	C0070035
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, April 05, 2011
Start Date/Time:	4/5/2011 9:30:00 AM
End Date/Time:	4/5/2011 11:00:00 AM
Last Inspection:	Tuesday, March 15, 2011

Inspector: <u>Karl Houskeeper.</u>
Weather: <u>Clear, Temp. 59 Deg. F.</u>
InspectionID Report Number: <u>2703</u>

Accepted by: jhelfric 4/12/2011

Permitee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY
Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current	Acreages	Mineral Ownership	Types of Operations		
323.95	Total Permitted	Federal		Underground	
202.00	Total Disturbed	☐ State		Surface	
5.35	Phase I	County		Loadout	
5.35	Phase II	▼ Fee		Processing	
	Phase III	Other	Y	Reprocessing	

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper,

Date

Tuesday, Apri

OIL, GAS & HINE

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 05, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 For PARTIAL inspections check only the elements evaluated.
 Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale			أأرا	
2.	Signs and Markers	V		7	
3.	Topsoil		411111	[]	e more
4.a	Hydrologic Balance: Diversions	y			proce.
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	Y	()	17	
4.c	Hydrologic Balance: Other Sediment Control Measures			D	
4.d	Hydrologic Balance: Water Monitoring			1]	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	7	Ž	7000M	
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	7		¥	
8.	Noncoal Waste	¥		. []	
9.	Protection of Fish, Wildlife and Related Environmental Issues	-			
10.	Slides and Other Damage		- Anna	- []	[1]
11.	Contemporaneous Reclamation				1
12.	Backfilling And Grading	:		O	
13.	Revegetation	-			10
14.	Subsidence Control				
15.	Cessation of Operations			Ĺ	1)
16.a	Roads: Construction, Maintenance, Surfacing	1 1			[""]
16.5	Roads: Drainage Controls		/		14.17%
17.	Other Transportation Facilities			D	
18.	Support Facilities, Utility Installations	[]			rans.
19.	AVS Check			[1]	1
20.	Air Quality Permit	10			
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070035 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 05, 2011

Page 3 of 3

2. Signs and Markers

The mine identification sign is located along side of the county road used as access into the permit area. The identification sign contains the required information.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appears stable. No visible hazards were observed. The refuse pile is being mined in lifts from east to west.